



**KOMITE NASIONAL KESELAMATAN TRANSPORTASI
REPUBLIC OF INDONESIA**

PRELIMINARY

KNKT.18.04.12.04

Aircraft Accident Investigation Report

PT. Lion Mentari Airlines

Boeing 737-800; PK-LOO

Djalaluddin Airport, Gorontalo

Republic of Indonesia

29 April 2018

2018

This Preliminary Report published by the Komite Nasional Keselamatan Transportasi (KNKT), Transportation Building, 3rd Floor, Jalan Medan Merdeka Timur No. 5 Jakarta 10110, Indonesia.

The report is based upon the initial investigation carried out by the KNKT in accordance with Annex 13 to the Convention on International Civil Aviation, the Indonesian Aviation Act (UU No. 1/2009) and Government Regulation (PP No. 62/2013).

The preliminary report consists of factual information collected until the preliminary report published. This report will not include analysis and conclusion.

Readers are advised that the KNKT investigates for the sole purpose of enhancing aviation safety. Consequently, the KNKT reports are confined to matters of safety significance and may be misleading if used for any other purpose.

As the KNKT believes that safety information is of greatest value if it is passed on for the use of others, readers are encouraged to copy or reprint for further distribution, acknowledging the KNKT as the source.

When the KNKT makes recommendations as a result of its investigations or research, safety is its primary consideration.

However, the KNKT fully recognizes that the implementation of recommendations arising from its investigations will in some cases incur a cost to the industry.

Readers should note that the information in KNKT reports and recommendations is provided to promote aviation safety. In no case is it intended to imply blame or liability.

Jakarta, June 2018

**KOMITE NASIONAL
KESELAMATAN TRANSPORTASI
CHAIRMAN**



SOERJANTO TJAHHJONO

TABLE OF CONTENTS

TABLE OF CONTENTS	i
TABLE OF FIGURES	iii
ABBREVIATIONS AND DEFINITIONS	iv
SYNOPSIS	vi
1 FACTUAL INFORMATION	1
1.1 History of the Flight.....	1
1.2 Injuries to Persons.....	3
1.3 Damage to Aircraft	3
1.4 Other Damage	4
1.5 Personnel Information	4
1.5.1 Pilot in Command.....	4
1.5.2 Second in Command	4
1.6 Aircraft Information.....	5
1.6.1 General	5
1.7 Meteorological Information.....	6
1.8 Aids to Navigation.....	8
1.9 Communications.....	9
1.10 Aerodrome Information	11
1.11 Flight Recorders.....	11
1.11.1 Flight Data Recorder (FDR).....	11
1.11.2 Cockpit Voice Recorder	11
1.12 Wreckage and Impact Information	12
1.13 Medical and Pathological Information	13
1.14 Fire.....	13
1.15 Survival Aspects	14
1.16 Tests and Research	14
1.17 Organizational and Management Information.....	14
1.17.1 PT. Lion Mentari Airlines	14
1.17.2 Djalaluddin Airport operator	15
1.17.3 BMKG Office at Djalaluddin	15
1.18 Additional Information	15
1.19 Useful or Effective Investigation Techniques	15

2	FINDINGS.....	16
3	SAFETY ACTION	18
4	SAFETY RECOMMENDATIONS	19
4.1	Djalaluddin Airport Operator	19
5	APPENDICES.....	21
5.1	Notice to pilot	21

TABLE OF FIGURES

Figure 1: The nose landing gear collapsed backward	3
Figure 2: Damage on the right engine cowling.....	3
Figure 3: Satellite weather image at 1015 UTC.....	7
Figure 4: Satellite weather image at 1022 UTC.....	7
Figure 5: Satellite weather image at 1030 UTC.....	7
Figure 6: RNAV procedure for runway 27	8
Figure 7: VOR/DME approach procedure runway 27	9
Figure 8: The main wheel marks and the last aircraft position	12
Figure 9: Left and right engine thrust reversers condition.....	13
Figure 10: The emergency exits and deployed slide on the right side of the aircraft	13

ABBREVIATIONS AND DEFINITIONS

ACC	:	Area Control Centre
AOC	:	Airline Operator Certificate
ARFF	:	Airport rescue and Fire Fighting
ATPL	:	Airline Transport Pilot License
AWOS	:	Automatic Weather Observation System
BMKG	:	<i>Badan Meteorologi, Klimatologi dan Geofisika</i> – (Meteorology, Climatology and Geophysics Agency of Indonesia)
C of A	:	Certificate of Airworthiness
C of R	:	Certificate of Registration
C	:	Celsius
CB	:	Cumulonimbus
CPC	:	Cabin Pressure Controller
CPL	:	Commercial Pilot License
CVR	:	Cockpit Voice Recorder
DGCA	:	Directorate General of Aviation
FA	:	Flight Attendant
FCOM	:	Flight Crew Operating Manual
FCTM	:	Flight Crew Training Manual
FDR	:	Flight Data Recorder
ft	:	Feet
hPa	:	Hectopascal
ICAO	:	International Civil Aviation Organization
KNKT	:	<i>Komite Nasional Keselamatan Transportasi</i> is the investigation authority of Indonesia also known as National Transportation Safety Committee (NTSC)
LT	:	Local Time
MHz	:	Mega Hertz
Nm	:	Nautical Miles
OVC	:	Overcast
PA	:	Passenger Address
PF	:	Pilot Flying
PIC	:	Pilot in Command
PM	:	Pilot Monitoring

psi	:	Pounds per square inch
RNAV/GNSS	:	Area Navigation / Global Navigation Satellite Systems is the aircraft capability that allows to navigate from point to point, defined by Latitude/Longitude and independent of any ground-based system
QFE	:	Query: Field Elevation
QNH	:	Query: Nautical Height / Query: Newlyn Harbour
QRH	:	Quick Reference Handbook
SIC	:	Second in Command
TBA	:	To be advised
UTC	:	Universal Coordinated Time
VOR	:	Very High Frequency Omni-Range
VOR/DME	:	Very High Frequency Omni-Range / Distance Measuring Equipment

SYNOPSIS

A Boeing B 373-900 registered PK-LOO was being operated by PT. Lion Mentari Airline (Lion Air) on 29 April 2018 as schedule passenger flight from Sultan Hasanuddin International Airport, Makassar to Djalaluddin Airport, Gorontalo. The Pilot in Command (PIC) acted as Pilot Monitoring (PM) and the Second in Command (SIC) acted as Pilot Flying (PF).

The pilot conducted instrument approach to runway 27 when heavy rain on the final and airport area. A pilot of an ATR aircraft that previously landed informed to the LNI 892 pilot that when they were making the approach, heavy rain on final area.

At 1040 UTC, the aircraft touched down, the spoiler automatically deployed and the PF selected the engine thrust reversers. The pilots felt that suddenly the rain became very heavy and only able to see the runway lights on the left side of the runway. The aircraft stopped on the left side runway shoulder at approximately 1,200 meters from the beginning runway 27 on heading 310. The nose landing gear collapsed.

After the aircraft stopped and completed the Emergency on Ground procedure the radio communication and passenger address system became unserviceable. The pilot commanded evacuation to FA 1 directly.

The FA 1 and FA 4 who were on the front cabin immediately opened the front doors and initiated the evacuation. The FA 2 and FA 3 who were on the aft cabin and the FA 5 who was on the center cabin did not notice that the passenger evacuation had been initiated.

The Djalaluddin Tower controller unable to communicate to the pilot however, the controller aware that the aircraft experienced abnormality. The controller notified the Airport Rescue and Fire Fighting (ARFF) by handy talky radio and the crash bell had not been connected to the new location of the ARFF station. The ARFF personnel after received notification immediately proceed to the position of aircraft stopped to assist the evacuation. No one injured on this accident and the aircraft had substantially damage.

KNKT issue safety recommendations to Djalaluddin Airport Operator to address identified safety issues.

The investigation is continuing and KNKT plans to complete the investigation within 12 months since the day of the occurrence. Should any further relevant safety issues emerge during the course of the investigation, KNKT will immediately bring the issues to the attention of the relevant parties and publish as required.

1 FACTUAL INFORMATION

1.1 History of the Flight

A Boeing 737-800 registered PK-LOO was being operated by PT. Lion Mentari Airlines (Lion Air) on 29 April 2018 as scheduled passenger flight from Sultan Hasanuddin International Airport, Makassar (WAAA) to Djalaluddin Airport Gorontalo¹ (WAMG) with flight number LNI 892. The Pilot in Command (PIC) acted as Pilot Flying (PF) and the Second in Command (SIC) acted as Pilot Monitoring (PM) on this flight. On board the flight were 181 persons, consisted of two pilots, five flight attendants and 174 passengers. The flight departed Sultan Hasanuddin International Airport, Makassar at 0928 UTC² (1728 LT) and cruised at altitude of 33,000 feet. The flight until commenced for descend was uneventful.

At 1008 UTC, the PM informed the Djalaluddin Tower controller that the flight maintained 33,000 feet and estimated time of arrival was 1040 UTC, thereafter the PM requested for weather information of Djalaluddin Airport. Djalaluddin Tower controller acknowledged the message and informed the weather conditions were wind calm, visibility 2,500 meters, weather slight rain, cloud³ FEW CB (cumulonimbus) 800 feet and overcast 800 feet, temperature 26°C, dew point 24 °C, QNH⁴ 1,008 hPa and QFE⁵ 1,006 hPa with additional remark that the CB on approach area.

At 1016 UTC, the PM informed the Djalaluddin Tower controller that the flight was descending to altitude of 25,000 feet and passed altitude of 29,000 feet and the aircraft position was on radial 211 at 84 Nm from Gorontalo. The PM requested clearance for descend to lower altitude. Djalaluddin Tower controller advised the pilot to fly direct to waypoint PRAMU⁶ and descend to altitude of 10,000 feet. The PM acknowledged the message and requested for the latest ground visibility and was informed that the visibility was 2,800 meters.

At 1025 UTC, the PM reported to Djalaluddin Tower controller the altitude was approaching 10,000 feet and was instructed to descend to 7,000 feet. A few minutes later the PM informed that the position was 12 Nm to waypoint PRAMU and approaching altitude 7,000 feet. The Djalaluddin Tower controller advised to maintain altitude 7,000 feet for a while.

1 Djalaluddin Airport Gorontalo will be named as Gorontalo for the purpose of this report.

2 UTC the 24-hour clock used in this report to describe the time of day as specific events occurred is in Coordinated Universal Time (UTC). Local time that be used in this report is Waktu Indonesia Tengah (WITA) or Central Indonesia Standard Time which is UTC +8 hours.

3 Cloud amount is assessed in total which is the estimated total apparent area of the sky covered with cloud. The international unit for reporting cloud amount for FEW is when the clouds cover 1/8 up to 2/8 area of the sky and overcast (OVC) is when the clouds all area of the sky.

4 QNH indicating the atmospheric pressure adjusted to mean sea level and when this value is set on an aircraft's altimeter, will cause the altimeter to read altitude above mean sea level within a certain defined region

5 QFE indicating the atmospheric pressure adjusted to aerodrome elevation and when this value is set on an aircraft's altimeter, will cause the altimeter to read altitude zero when the aircraft on ground.

6 Waypoint PRAMU is located at about 17 Nm on bearing 136° from Gorontalo.

At 1028 UTC, Djalaluddin Tower controller advised the pilot to descend to altitude of 5,800 feet and issued clearance to make VOR/DME approach runway 27 then advised to report when leaving waypoint PRAMU. The PM acknowledged the message.

At 1030 UTC, the PM reported that the aircraft was descending from altitude of 5,800 feet and leaving waypoint PRAMU. The Djalaluddin Tower controller advised the pilot to report when runway was in sight.

At 1032 UTC, Djalaluddin Tower controller informed the pilot that rain over the field and requested the aircraft position. The PM acknowledged the information and reported that the aircraft was on final course runway 27.

At 1033 UTC, a pilot of an ATR aircraft that previously landed informed to the LNI 892 pilot that when they were making the approach, the final area was heavy rain. The PM acknowledged the information. There was no pilot discussion to anticipate the reported heavy rain.

The Djalaluddin Tower controller informed the pilot that the wind direction was 150° with velocity of 7 knots, QNH 1,008 hPa and issued landing clearance if the pilot able to see the runway. The PM acknowledged the message and would inform when they were able to see the runway.

The pilot requested for high intensity of runway light to the controller and was informed that the runway light had been set to maximum intensity.

At 1034 UTC, the PM informed the Djalaluddin Tower controller that the runway was in sight. The Djalaluddin Tower controller then issued landing clearance for LNI 892 since the controller was able to see the aircraft landing light.

At 1040 UTC, the aircraft touched down, the autobrake operated, the spoiler automatically deployed and the PF selected the engine thrust reversers. The pilots felt that suddenly the rain became very heavy and only able to see the runway lights on the left side of the runway. The crew felt the aircraft impact and stopped. The aircraft stopped on the left side runway at approximately 1,200 meters from the beginning runway 27 and the last aircraft heading was 310°.

The pilot attempted to contact the Djalaluddin Tower controller but was not received by the controller. The Djalaluddin Tower controller was also attempted to contact the pilot, but the pilot did not receive the controller message.

The Djalaluddin Tower controller could not clearly see the aircraft position however, the controller aware that the aircraft experienced abnormality. The controller notified the Airport rescue and Fire Fighting (ARFF) by handy talky radio. The crash bell had not been connected to the ARFF station since the ARFF station moved to the new location few months before.

The ARFF personnel immediately proceed to the position of aircraft stopped to assist the evacuation after received the notification.

All passengers were evacuated using escape slides on the forward cabin doors.

1.2 Injuries to Persons

No one injured as a result of this accident.

1.3 Damage to Aircraft

The aircraft substantially damaged. The nose landing gear collapsed backward and impacted the forward lower fuselage resulting in dent on this area. The engine cowlings were broken.



Figure 1: The nose landing gear collapsed backward



Figure 2: Damage on the right engine cowling

1.4 Other Damage

Two runway lights damaged after impacted with the aircraft.

1.5 Personnel Information

1.5.1 Pilot in Command

Gender	: Male
Age	: 57 years old
Nationality	: Indonesian
Marital status	: Married
Date of joining company	: 15 January 2003
License	: ATPL
Date of issue	: 6 June 1991
Aircraft type rating	: Boeing 737 NG
Instrument rating validity	: 31 May 2019
Medical certificate	: First class
Last of medical	: 23 November 2017
Validity	: 23 May 2018
Medical limitation	: TBA
Last line check	: 12 June 2017
Last proficiency check	: 9 April 2018
Flying experience	
Total hours	: 24,863 hours
Total on type	: 8,585 hours
Last 90 days	: 271 hours
Last 60 days	: 175 hours
Last 24 hours	: 3 hours 50 minutes
This flight	: 1 hour 12 minutes

1.5.2 Second in Command

Gender	: Male
Age	: 24 years old
Nationality	: Indonesian
Marital status	: Single

Date of joining company : 26 December 2015
 License : CPL
 Date of issue : 7 May 2014
 Aircraft type rating : Boeing 737 NG
 Instrument rating validity : 30 June 2018
 Medical certificate : First class
 Last of medical : 6 April 2018
 Validity : 6 October 2018
 Medical limitation : TBA
 Last line check : -
 Last proficiency check : 19 June 2017

Flying experience

Total hours : 2,188 hours 22 minutes
 Total on type : 2,188 hours 22 minutes
 Last 90 days : 247.85 hours
 Last 60 days : 160.35 hours
 Last 24 hours : 3 hours 50 minutes
 This flight : 1 hour 12 minutes

1.6 Aircraft Information

1.6.1 General

Registration Mark : PK-LOO
 Manufacturer : Boeing Company
 Country of Manufacturer : United states of America
 Type/Model : Boeing 737-8GP
 Serial Number : 39814
 Year of Manufacture : 2014
 Certificate of Airworthiness
 Issued : 28 April 2018
 Validity : 27 April 2019
 Category : Transport
 Limitations : None
 Certificate of Registration
 Registration Number : 3461

Issued : 28 April 2017
 Validity : 27 April 2020
 Time Since New : 10,661 hours
 Cycles Since New : 7,960 cycles
 Last Major Check : C01 (2 Agustus 2017)
 Last Minor Check : P-12 (18 April 2018)

1.7 Meteorological Information

The weather information provided by Badan Meteorologi, Klimatologi dan Geofisika – BMKG (Meteorology, Climatology and Geophysics Agency of Indonesia) station Djalaluddin, Gorontalo. The weather observation was performed every 30 minutes in normal condition, while significant weather changes, the observation would be performed every 15 minutes.

The weather reports issued on 29 April 2018 were as follow:

		1000 UTC	1030 UTC	1100 UTC
Wind	:	050° / 02 knots	150° / 05 knots	070° / 05 knots
Visibility	:	6 km	6 km	6 km
Weather	:	RA (rain)	RA	RA
Cloud	:	FEW CB 800 feet / OVC 800 feet	FEW CB 800 feet / OVC 800 feet	FEW CB 800 feet / OVC 800 feet
Temperature	:	26°C	25°C	25°C
Dewpoint	:	24°C	24°C	24°C
QNH	:	1,008 hPa	1,008 hPa	1,009 hPa
QFE	:	1,006 hPa	1,006 hPa	1,007 hPa
Remark	:	CB on approach area	CB on approach area	CB on approach area
Trend	:	No significant	No significant	No significant

The satellite weather images recorded by meteorology station in Gorontalo were as follows:




Figure 3: Satellite weather image at 1015 UTC




Figure 4: Satellite weather image at 1022 UTC




Figure 5: Satellite weather image at 1030 UTC

1.8 Aids to Navigation

GORONTALO equipped with Very High Frequency Omni Range (VOR) identified as GTO broadcast on frequency 113.5 MHz.

The instrument approach procedures for runway 27 were VOR/DME approach⁷ and RNAV/GNSS⁸ approach.




Figure 6: RNAV procedure for runway 27

⁷ VOR/DME approach (Very High Frequency Omni-Range / Distance Measuring Equipment) is the instrument approach procedure when the track and distance refer to the VOR ground base navigation aid.

⁸ RNAV/GNSS (Area Navigation/ Global Navigation Satellite Systems) is the aircraft capability that allows to navigate from point to point, defined by Latitude/Longitude and independent of any ground-based system.




Figure 7: VOR/DME approach procedure runway 27

1.9 Communications

All communications between air traffic controller and the pilots were recorded by ground based automatic voice recording equipment and Cockpit Voice Recorder (CVR) for the duration of the flight. The quality of the aircraft's recorded transmissions was good.

The excerpt of communication between the Djalaluddin Tower controller and the pilot is as follow:

At 1008 UTC, the pilot informed the Djalaluddin Tower controller (controller) that they were maintaining altitude of 33,000 feet, on radial 212 from GTO (VOR) and estimate time of arrival was 1040 UTC. The pilot requested for weather information.

The controller informed the weather condition was wind calm, visibility 2,500 meters, weather slight rain, cloud FEW CB 800 feet and overcast 800 feet, temperature 26°C, dew point 24°C, QNH 1,008 hPa, QFE 1,006 hPa and remark the CB in approach area.

At 1016 UTC, the pilot reported that the flight was descending to altitude of 25,000 feet and passed altitude of 29,000 feet, and the aircraft position was on radial 211 at 84 Nm from Gorontalo. The pilot requested clearance for descend to lower altitude. The controller advised the pilot to fly direct to waypoint PRAMU and descend to altitude 10,000 feet.

The pilot acknowledged the message and requested for the latest ground visibility. The controller informed that the visibility was 2,800 meters.

At 1025 UTC, the pilot reported to the controller that the altitude was approaching 10,000 feet and was instructed to descend to 7,000 feet.

A few moments later the pilot informed that the aircraft position was 12 Nm to waypoint PRAMU and approaching altitude 7,000 feet. The controller advised to maintain 7,000 feet for a while.

At 1028 UTC, the controller advised the pilot to descend to 5,800 feet and issued clearance to make VOR/DME approach runway 27 then advised to report when leaving waypoint PRAMU. The PM acknowledged the message.

At 1030 UTC, the pilot reported that the aircraft was descending from altitude of 5,800 feet and leaving waypoint PRAMU. The controller advised the pilot to report when the runway in sight.

At 1032 UTC, the controller informed that rain over the field and requested position of the aircraft. The pilot acknowledged the information and reported that the aircraft was on final course runway 27.

At 1033 UTC, a pilot of an ATR aircraft that previously landed informed to the LNI 892 pilot that when they were making the approach the final area was heavy rain. The pilot acknowledged the information.

The controller informed that the wind direction was 150° with velocity of 7 knots, QNH 1,008 hPa and issued landing clearance when the runway was in sight. The pilot acknowledged the message and would inform when runway was in sight.

At 1034 UTC, the pilot reported that the runway was in sight and the controller issued landing clearance.

At 1036 UTC, the controller confirmed whether the aircraft position was on the grass.

At 1038 UTC, the controller confirmed whether the pilot requiring any assistant.

After the aircraft stopped, both controller and pilot attempted to communicate and failed. The pilot also attempted to make announcement through passenger address system which was also failed.

1.10 Aerodrome Information

Airport Name	: Djalaluddin Airport
Airport Identification	: WAMG / GTO
Airport Operator	: Directorate General of Civil Aviation (DGCA)
Coordinate	: 0°38'14" N; 122°50'55" E
Elevation	: 124 feet
Runway Direction	: 09 – 27 (094° – 274°)
Runway Length	: 2,500 meters
Runway Width	: 45 meters
Surface	: Asphalt

1.11 Flight Recorders

The aircraft was equipped with Flight Data Recorder (FDR) and Cockpit Voice Recorder (CVR). Both recorders recovered from the aircraft and transported to KNKT recorder facility for data download process.

1.11.1 Flight Data Recorder (FDR)

The FDR data are as follows:

Manufacturer	: Honeywell
Type/Model	: Solid state
Part Number	: 980-4750-009
Serial Number	: 02878

The FDR data was successfully downloaded. The FDR contained data of 1,274 parameters of 53 hours and 40 minutes or 31 flight sectors including the accident flight. The detail information of the FDR will be included in the final report.

1.11.2 Cockpit Voice Recorder

The CVR data are as follow:

Manufacturer	: Honeywell
Type/Model	: Solid state
Part Number	: 980-6022-001
Serial Number	: 120-16054

The CVR data was successfully downloaded. The CVR contained data of two hours and four minutes consisted of one hour 34 minutes of standard quality data and 30 minutes good quality data of four channels including the accident flight. The detail information of the CVR will be included in the final report.

1.12 Wreckage and Impact Information

The touch down mark could not be determined. Based on the marks of the main wheel, it was likely that the aircraft touched down on the touchdown zone and on the center line.



Figure 8: The main wheel marks and the last aircraft position

Both engine thrust reversers were on deploy position. Muds were found on both engine intakes and the thrust reverser doors, while the engine exhausts were clean of mud.



Figure 9: Left and right engine thrust reversers condition

The flaps were found on full down position.

The left and right front door escape slides were deployed, while the over-wing exit windows and aft doors were close.



Figure 10: The emergency exits and deployed slide on the right side of the aircraft

1.13 Medical and Pathological Information

After the accident, alcohol and drug test were performed to all crew, the result indicated that all crew were not affected by drug or alcohol.

1.14 Fire

There was no evidence of fire in-flight or post-impact fire.

1.15 Survival Aspects

After the aircraft stopped, the pilots commanded “*Attention Crew on Station*”, followed by the flight attendants checking the outside condition through the viewing windows. The FA 5 who were on the aft cabin, moved to the center cabin and checked the outside condition through the passenger windows. All flight attendants did not see any hazard to open all emergency exits in case the evacuation required.

After commanded “*Attention Crew on Station*”, the pilots performed Emergency on the Ground procedure. One item on the procedure required pilot decision to command evacuation. The PIC then commanded the SIC to command evacuation. The SIC commanded evacuation to the FA 1 using passenger address (PA) system but the PA system did not functioning. The PIC asked the SIC to knock on the cockpit door and open it to command for evacuation directly to the FA 1. The SIC did as it told.

The FA 1 received the command for evacuation and passed it to the FA 4 and both flight attendants immediately opened the forward cabin doors, deployed the escape slides and initiated the passenger evacuation. Both FA shouted to the passengers to evacuate immediately.

During the evacuation, the flight attendant noticed the ARFF arrived and assisted the evacuation from the outside. The ARFF personnel advised the passengers to slow down the evacuation.

Most of the passengers stood up and block the view toward the front cabin made the FA 2 and FA 3 who were on the aft cabin and the FA 5 who was on the center cabin did not notice the passenger evacuation had been initiated. They only noticed that the passengers were slowly moving forward and assumed normal disembarkation initiated.

The flight attendants noticed that the area surround aircraft was dark and the lighting was only from the ARFF vehicles.

1.16 Tests and Research

Upon the issuance of this preliminary report, no test or research was conducted. Any test or research conducted during the investigation, the result will be included in the final report.

1.17 Organizational and Management Information

1.17.1 PT. Lion Mentari Airlines

Aircraft Owner	:	SMBC Aviation Capital Limited
Address	:	IFSC House, IFSC, Dublin 1, Ireland
Aircraft Operator	:	PT. Lion Mentari Airlines, Indonesia (Lion Air)
Address	:	Jl. Gajah Mada No. 7, Jakarta Pusat, Indonesia
AOC Number	:	AOC 121-010

Lion Air operated total of 116 aircrafts consisting of 3 Airbus A330, 35 Boeing 737 - 800, 70 Boeing 737-900ER, and 8 Boeing 737 MAX, which served more than 120 destinations, domestic and international, and operated up to 630 flights daily.

1.17.2 Djalaluddin Airport operator

Djalaluddin Airport operated by the Directorate General of Civil Aviation (DGCA). Detail information of the airport operator including the procedure will be included in the final report.

1.17.3 BMKG Office at Djalaluddin

The meteorological services for Djalaluddin Airport were provided by BMKG office station Gorontalo.

Other than visual observation by meteorology observer, the weather was also observed with Automatic Weather Observation System (AWOS). The AWOS information provided to the controller on a display in tower cab.

Since 25 April 2018, the AWOS system was unserviceable and BMKG office station Gorontalo and Airnav Indonesia Branch Office Gorontalo established a media communication to distribute weather information.

The unserviceable AWOS had made up date weather information did not available in the tower cab. The controller should call to BMKG observer requesting the update weather information.

1.18 Additional Information

The investigation is continuing and KNKT plans to complete the investigation within 12 months since the day of the occurrence. Should any further relevant safety issues emerge during the course of the investigation, KNKT will immediately bring the issues to the attention of the relevant parties and publish as required.

1.19 Useful or Effective Investigation Techniques

The investigation was conducted in accordance with the KNKT approved policies and procedures, and in accordance with the standards and recommended practices of Annex 13 to the Chicago Convention.

2 FINDINGS⁹

According to factual information during the investigation, the KNKT identified initial findings as follows:

1. The aircraft had valid Certificate of Airworthiness (C of A) and Certificate of Registration (C of R).
2. The pilots held valid licenses and medical certificates.
3. On the first contact, when the aircraft was maintained 33,000 feet, the weather condition reported was wind calm, visibility 2,500 meters, weather slight rain, cloud FEW CB (cumulonimbus) 800 feet and overcast 800 feet, with additional remark that the CB on approach area. The weather condition was above the minima requirement for instrument approach runway 27.
4. A pilot of an ATR aircraft that previously landed informed to the LNI 892 pilot that when they were making the approach the final area was heavy rain. The LNI 892 pilot acknowledged the information.
5. The Automatic Weather Observation System (AWOS) of the meteorology station Gorontalo was unserviceable 5 days before the accident flight. The unserviceable AWOS had made up date weather information did not available in the tower cab. The controller should call to BMKG observer requesting the update weather information.
6. At 1040 UTC, the aircraft touched down, the spoiler automatically deployed and the PF selected the engine thrust reversers. The pilots felt that suddenly the rain became very heavy and only able to see the runway lights on the left side of the runway.
7. The aircraft stopped on the left side runway shoulder at approximately 1,200 meters from the beginning runway 27 and the aircraft heading was 310°.
8. After completion of the Emergency on Ground procedure, the pilot unable to communicate with the controller and the Passenger Address system did not work. The instruction for evacuation was provided verbally direct to the Flight Attendant 1 (FA 1).
9. The FA 1 and FA 4 initiated the passenger evacuation from the forward cabin doors, while FA 5 who was on the center cabin and FA 2 and FA 3 who were on the aft cabin did not know that the passenger evacuation had been initiated and did not initiated passenger evacuation.
10. The Djalaluddin Tower controller could not clearly see the aircraft position however, the controller aware that the aircraft experienced abnormality. The controller notified the Airport rescue and Fire Fighting (ARFF) by handy talky radio since the crash bell had not been connected to the new location of the ARFF station.

⁹ Findings are statements of all significant conditions, events or circumstances in the accident sequence. The findings are significant steps in the accident sequence, but they are not always causal, or indicate deficiencies. Some findings point out the conditions that pre-existed the accident sequence, but they are usually essential to the understanding of the occurrence, usually in chronological order.

11. The ARFF personnel after received notification immediately proceed to the position of aircraft stopped to assist the evacuation.
12. No one injured in this accident and the aircraft substantially damaged. The nose landing gear collapsed backward and impacted the forward lower fuselage resulted in dent on this area. The engine cowlings broken. Two runway lights were found broken.

3 SAFETY ACTION

At the time of issuing this Preliminary Report, the KNKT had been informed of safety actions taken by aircraft operator resulting from this accident. The safety actions consisted of corrective training for both pilots including simulator training and flight attendants on duty which focused on emergency procedure.

The Safety and Security Directorate issued safety recommendations for related department:

1. To add scenario on recurrent simulator for all pilots, including tire-cornering and wave-off exercises.
2. To revise all the OM-C that states “No take-off or landing in heavy rain. When the RWY is contaminated” to “No take-off or landing in heavy rain or when the RWY is contaminated”
3. To revise the OM-C on WAMG/GTO for VOR DME approach RWY 27 into step by step procedures and specified the final approach fix is changed to the 12 Nm point (CF27) and landing configuration has been achieved.
4. Obtain approval from regulator (DGCA) for Lion Air of RNAV (GNSS) approach.
5. to review evacuation procedure.
6. To determine alternate signal for command “evacuate” when PA/interphone communication system suddenly failed, to the following example of, in the condition such FA1 identify that PA system is fail to function, immediately she/he will use megaphone to initiate evacuation command.
7. To include “increasing situational awareness in any abnormal condition” into ‘one-minute silent review’ item.

The Safety and Security Directorate also issued Safety Information for all pilots (detail is attached on the Appendices of this report) contained:

1. To respect of Stabilization Approach criteria
2. To respect of Mandatory Missed Approach criteria
3. To increase awareness when weather deterioration occurs such as time by time visibility reduction
4. To ensure, implement anything related to requirement, prohibition or limitation stated in OM-C
5. To review crew coordination and standard call out during approach
6. To increase crew assertiveness, particularly as pilot monitoring

4 SAFETY RECOMMENDATIONS

KNKT acknowledge the safety actions taken by aircraft operator and consider that the safety actions were relevant to improve the safety of the operation.

KNKT issued safety recommendations airport operator to address safety issues identified in this report.


4.1 Djalaluddin Airport Operator


- **04.B-2018-12.1**

The crash bell had not been connected to the Airport Rescue and Fire Fighting (ARFF) station. KNKT recommend Djalaluddin Airport Operator to establish all equipment required for the standard airport services.


5 APPENDICES

5.1 Notice to pilot

	SAFETY AND SECURITY DIRECTORATE	03/SS/SINF/V/2018
	INFORMATION	[03/05/2018]

Issued date:	03 rd May 2018	
Applicability:	ALL LION AIR PILOTS	
Distribution list:	SAFETY COORPORATE, DO, OF, DE, DQ,GO	
Prepared by:	FDA Team	Signature 
Verified by:	SF	
Approved by:	DS	

Subject:	RUNWAY EXCURSION LION AIR IN GORONTALO
----------	---



SMALL ACTION BIG REVOLUTION
LOOK HAZARD - DEFINE RISK - REPORT IT!

CORUSON
WEBSITE & MOBILE APPS
Coruson
SMS TEXT / WA
+62 812 8029 8209
EMAIL
ssu_reports@lionair.co.id

Send your Report with "ADDER" Information Form.
The Report Will be Confidential and Protected by Company Policy

Dear All Pilots

On 29th April 2018 Lion Air B737-800 with registration PK-L00 performing flight route from Makassar (UPG) to Gorontalo (GTO) was land in rain condition, veer-off/excursion to the left side of runway approximately stop at mid distance. Half of the aircraft on the runway pavement, while the other half beyond runway edge. Nose landing gear damage found. Evacuation process went well without any injuries for both passengers and crews.



As we are waiting for result of the undergoing investigation, therefore Lion Air Safety Department would like to remind and emphasize all flight crew as follow:

1. To respect of Stabilization Approach criteria
2. To respect of Mandatory Missed Approach criteria
3. To increase awareness when weather deterioration occurs such as time by time visibility reduction
4. To ensure, implement anything related to requirement, prohibition or limitation stated in OM-C
5. To review crew coordination and standard call out during approach
6. To increase crew assertiveness, particularly as pilot monitoring

Hopefully this information will increase our safety awareness. Thank you.

The content of this document is not intended for publication purpose and not to be reproduced in a whole or in part without the written authority of the Lion Air Safety and Security Directorate.

KOMITE NASIONAL KESELAMATAN TRANSPORTASI REPUBLIK INDONESIA

Jl. Medan Merdeka Timur No.5 Jakarta 10110 INDONESIA

Phone : (021) 351 7606 / 384 7601 Fax : (021) 351 7606 Call Center : 0812 12 655 155

website 1 : <http://knkt.dephub.go.id/webknkt/> website 2 : <http://knkt.dephub.go.id/knkt/>

email : knkt@dephub.go.id